

How to optimally use an automatic watch winder for my OMEGA watch?

To wind OMEGA watches automatically, we recommend a winder from our leather accessories collection. You can discover them at:

http://www.omegawatches.com/accessories/fine-leather/watch-boxes/

If you have a different winder, we indicate below the number of revolutions required per day, to ensure a minimum power reserve of at least 30 hours after removing the watch from the winder.

Please take note that we cannot guarantee the safe operation of equipment which has not been recommended by OMEGA.

The calibre (movement) of your watch is indicated by a pictogram on the pictogram card.

The below table indicates the number of rotations and winding direction recommended according to the calibre:

Number of	Winding direction	Calibre
rotations per day		
540	Anticlockwise	2601
600	Clockwise	2600, 3202, 3205, 3301, 3303, 3313,
		3603, 3612
720	Bidirectional	8400, 8401, 8402, 8403, 8421, 8500,
		8501, 8507, 8508, 8520, 8521, 8601,
		8611, 8602, 8612, 8605, 8615, 8900,
		8901, 8902, 8903, 8906, 8907, 8912,
		8913, 9300, 9301, 9605, 9615, 9900,
		9901, 9904, 9905
800	Bidirectional	1120, 1128, 1138, 2200, 2202, 2300,
		2403, 2500, 2507, 2610, 2627, 2628,
		3220, 3601, 3602
800	Clockwise	1151, 1152, 1164, 3304, 3330, 3606,
		3888, 3890
860	Clockwise	2520
910	Clockwise	2005

Manually wound calibers are obviously not affected by this notice.

