

MEASUREMENTS RELATING TO WATCH MOVEMENTS

Size	Lignes	MM.	Inches	Size	Lignes	MM.	Inches
28/0	3.01	6.78	.267	7	15.76	35.56	1.400
27/0	3.38	7.62	.300	8	16.14	36.40	1.433
26/0	3.75	8.46	.333	9	16.52	37.26	1.467
25/0	4.13	9.32	.367	10	16.89	38.10	1.500
24/0	4.50	10.16	.400	11	17.26	38.94	1.533
23/0	4.88	11.00	.433	12	17.64	39.80	1.567
22/0	5.26	11.86	.467	13	18.02	40.64	1.600
21/0	5.63	12.70	.500	14	18.39	41.48	1.633
20/0	6.00	13.54	.533	15	18.77	42.34	1.667
19/0	6.38	14.40	.567	16	19.14	43.18	1.700
18/0	6.76	15.24	.600	17	19.51	44.02	1.733
17/0	7.13	16.08	.633	18	19.90	44.88	1.767
16/0	7.51	16.94	.667	19	20.27	45.72	1.800
15/0	7.88	17.78	.700	20	20.64	46.56	1.833
14/0	8.25	18.62	.733	21	21.02	47.42	1.867
13/0	8.64	19.48	.767	22	21.39	48.26	1.900
12/0	9.01	20.32	.800	23	21.77	49.10	1.933
11/0	9.38	21.16	.833	24	22.15	49.96	1.967
10/0	9.76	22.02	.867	25	22.52	50.80	2.000
9/0	10.13	22.86	.900	26	22.89	51.64	2.033
8/0	10.51	23.70	.933	27	23.27	52.50	2.067
7/0	10.89	24.56	.967	28	23.65	53.34	2.100
6/0	11.26	25.40	1.000	29	24.02	54.18	2.133
5/0	11.63	26.24	1.033	30	24.40	55.04	2.167
4/0	12.01	27.10	1.067	31	24.77	55.88	2.200
3/0	12.39	27.94	1.100	32	25.18	56.72	2.233
2/0	12.76	28.78	1.133	33	25.53	57.58	2.267
0	13.14	29.64	1.167	34	25.90	58.42	2.300
1	13.51	30.48	1.200	35	26.27	59.26	2.333
2	13.88	31.32	1.233	36	26.65	60.12	2.367
3	14.27	32.18	1.267	37	27.01	60.96	2.400
4	14.64	33.02	1.300	38	27.40	61.80	2.433
5	15.02	33.88	1.333	39	27.78	62.66	2.467
6	15.39	34.72	1.367	40	28.15	63.50	2.500